

GRAFFITI

Mostra

Lateral wall built in carbonated sandstone. Santa Maria la Mayor church. Alcañiz. Teruel. Spain.

Causes de la patologia

Mechanical anthropic action.

Imatge de visu



Autor: Manuel Iglesias

Descripció: Carved figure, named below, (right) and schematic representation of a house (left) on the surface of an ashlar,

Imatge detall / macro



Autor: Manuel Iglesias

Augments: scale

Descripció: Detail of the house. The incision of the carving has slightly rounded edges suggesting certain antiquity.

Bibliografia

ICOMOS-ICS (2008). Illustrated glossary on stone deterioration pattern.

http://international.icomos.org/publications/monuments_and_sites/15/pdf/Monuments_and_Sites_15_ISCS_Glossary_Stone.pdf

ORDAZ, J., & ESBERT, R. (1988). Glosario de términos relacionados con el deterioro de las piedras de construcción. *Materiales de Construcción*, 38 (209): 39-45. doi: 10.3989/mc.1988.v38.i209.847

Autor

Manuel Iglesias Campos. manuel.iglesias@cetec-patrimoni.com

Restorer

Institució o Empresa

