

# BLACK SPOTS

## Sample

Bust of calcarenite. Sta. Clotilde. Blanes. Catalunya. Spain


---

## Pathology Causes

Atac biològic. Es tracta de restes de cèrquells adhesius de *Parthenocissus quinquefolia* (vinya verge).

---

## Visual Image



**Author:** Sta.Clotilde Gardens. Blanes

**Description:** Scattered black spots, occasionally grouped. Rough texture to the touch. It is located in the back of the bust has a concavity

---

## Image detail / macro



**Author:** Cetec-p. Josep Girbal

**Magnification:** x 50

**Description:** Strongly adhesive disks holding the stone. Some have a woody type prominences.

---

## Associated Pathologies

Chromatic changes

---

## Bibliography

Masclans, F.: Els noms de les plantes als Països Catalans. Centre Excursionista de Catalunya. Granollers-Barcelona, 1981.

Masalles, R.M. et al.: Història Natural dels Països Catalans. Enciclopèdia Catalana. Barcelona, 1988.

---

### **Author**

Montserrat Puges Dorca. mpuges@bcn.cat

Restauradora

---

### **Institution or Company**

Servei d'Arqueologia. Ajuntament de Barcelona

---