

BLACK SPOTS


Sample

Bust of calcarenite. Sta. Clotilde. Blanes. Catalunya. Spain

Pathology Causes

Atac biològic. Es tracta de restes de cèrquells adhesius de *Parthenocissus quinquefolia* (vinya verge).

Visual Image



Author: Sta.Clotilde Gardens. Blanes

Description: Scattered black spots, occasionally grouped. Rough texture to the touch. It is located in the back of the bust has a concavity

Image detail / macro



Author: Cetec-p. Josep Girbal

Magnification: x 50

Description: Strongly adhesive disks holding the stone. Some have a woody type prominences.

Associated Pathologies

Chromatic changes

Bibliography

Masclans, F.: Els noms de les plantes als Països Catalans. Centre Excursionista de Catalunya. Granollers-Barcelona, 1981.

Masalles, R.M. et al.: Història Natural dels Països Catalans. Enciclopèdia Catalana. Barcelona, 1988.

Author

Montserrat Puges Dorca. mpuges@bcn.cat

Restauradora

Institution or Company

Servei d'Arqueologia. Ajuntament de Barcelona
