

# BLACK SPOTS

## Muestra

Bust of calcarenite. Sta. Clotilde. Blanes. Catalunya. Spain

---

## Causas de la patología

Atac biològic. Es tracta de restes de circells adhesius de *Parthenocissus quinquefolia* (vinya verge).

---

## Imagen de visu



**Autor:** Sta.Clotilde Gardens. Blanes

**Descripción:** Scattered black spots, occasionally grouped. Rough texture to the touch. It is located in the back of the bust has a concavity

---

## Imagen detalle / macro



**Autor:** Cetec-p. Josep Girbal

**Aumentos:** x 50

**Descripción:** Strongly adhesive disks holding the stone. Some have a woody type prominences.

---

## Patologías Asociadas

Chromatic changes

---

## Bibliografía

Masclans, F.: Els noms de les plantes als Països Catalans. Centre Excursionista de Catalunya. Granollers-Barcelona, 1981.

Masalles, R.M. et al.: Història Natural dels Països Catalans. Enciclopèdia Catalana. Barcelona, 1988.

---

### **Autor**

Montserrat Puges Dorca. mpuges@bcn.cat

Restauradora

---

### **Institución o Empresa**

Servei d'Arqueologia. Ajuntament de Barcelona

---